

## Annual compliance summary 2002/2003 for boatsheds in the Wellington Region

The annual compliance inspections for 2002/2003 boatsheds in the Wellington Region have been completed.

There are 133 boatsheds in the Wellington Region. A summary of the inspections is as follows:

### Summary of Compliance Inspections

Location	Total boatsheds	Internal inspections	External only	Fully complying	Non complying
Evans Bay/ Eastbourne/ Worser Bay/ Karaka Bay	26	24	2	22	2
Paremata/ Pauatahanui	28	24	4	27	1
Camborne	36	24	12	18	6
Onepoto/ Titahi Bay	43	29	14	29	0
<b>TOTAL</b>	<b>133</b>	<b>101</b>	<b>32</b>	<b>92</b>	<b>9</b>

- From the 101 internal inspections that were carried out, nine boatshed owners were rated Non Complying.
- Of the 101 boatsheds internally inspected, nine boatshed owners are not using their boatsheds for storing boats or boating equipment, which means that they are not complying with condition 1 or 6 of their consent conditions. These consent holders have therefore received an overall compliance rating on *Non Complying*.
- 32 boatsheds were not inspected, as the owners either did not respond to letters sent out arranging appointments or the owners have changed address and could not be contacted.
- Of these 32 boatsheds, many are in very poor condition and the owners need to be contacted urgently. Some are also suspected of using for overnight stays.
- Out of the *Fully Complying* category, two boatshed owners were discharging from sinks to the CMA. These consent holders are in breach of section 15(a) of the RMA and were requested to rectify the situation as soon as possible.